

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 99.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-024845**Date Inspected:** 12-Jun-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC) Chanxing Island**Location:** Shanghai, China**CWI Name:** Mr. Shi Lei**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segment**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance Inspector (QA), Vibin Kumar Selvanayaham, was present during the times noted above for observations relative to the work being performed.

**Magnetic Particle Testing (MT)**

This QA inspector witnessed and performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The members are identified as OBG Segment 13AW.

The weld designations reviewed/witnessed are as follows:

1. SEG3013H – 175, 176, 178, 189, 190, 192
2. SEG3013H – 216, 221, 230, 244
3. SEG3013AU – 022, 026, 028, 033, 054
4. SEG3013AW – 004, 003, 04 004, 003, 041, 042
5. SEG3013AW – 093, 094, 044, 007, 008, 061, 059

OBG Trial Assembly Yard

This QA Inspector observed the following work in progress:

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

Shielded Metal Arc Welding (SMAW) welding of weld joint SEG3011C-099 located on Bottom Panel stiffener to Floor beam of OBG Segment 13CE. ZPMC Welder is identified as 068924. ZPMC Quality Control (QC) is identified as Mr. Lv Li Qing. The welding variables recorded by QC appeared to comply with the Applicable WPS-345-SMAW-1G-(1F)-FCM-Repair, which is used as per Welding Repair Report (WRR) B-WRR-21123.

SMAW welding of weld joint OBE14G-004 located on 14E of OBG Segment 14E. ZPMC Welder is identified as 501946. ZPMC Quality Control (QC) is identified as Mr. Zhu Yuan. The welding variables recorded by QC appeared to comply with the Applicable WPS-B-P-2114-FCM-1.

SMAW welding of weld joint OBE14A-011 located on drain plate of OBG Segment 14E. ZPMC Welder is identified as 044779. ZPMC Quality Control (QC) is identified as Mr. Zhu Yuan. The welding variables recorded by QC appeared to comply with the Applicable WPS-B-P-2113-FCM-1.

SMAW welding of weld joint OBE14A-016 located on drain plate of OBG Segment 14E. ZPMC Welder is identified as 216086. ZPMC Quality Control (QC) is identified as Mr. Wang Li Yang. The welding variables recorded by QC appeared to comply with the Applicable WPS-B-P-2114-FCM-1.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

### Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact , who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Kumar,Vibin	Quality Assurance Inspector
<b>Reviewed By:</b>	Patel,Hiranch	QA Reviewer

---